Berth Holders concern raised with Barry Davies on 20.4.22	Decrease from Device	A -4: ·
Concern	Response from Barry Davies	Actions
Toilets		
Dirty with mould in several places.	Will raise with CHT -daily inspection by Dock Master	
Current cleaning regime inadequate		
Toilet block is remote,no immediate help if needed	Consider expanding CCTV - above outer door	
Separate m and f facilities	Revisit the plans/drawings .Costings in summer months	
Number of toilets	Temp facilities during peak periods	
	The state of the s	
Watkin Jones	Not considered	
Storm Gates		
Can storm boards be fitted?	no as crane would be needed.	
	Possibility of a "wave break " pontoon	
Pollution	Filtering system would require specialist input	
Cadnant - emergency overflow - reducing or filtering	Need to enquire with DC and WW	
inflow on NE corner may be from roads -a lot of litter/rubbish	Berth holders need to report with photographs	
Parking		
Can permits be issued in March for 2023?	Will consult with marina managers	
Security		
People, especially youngsters accessing the north side by	Will investigate but note it is a challenging to prevent	
climbing over gate.	unauthorised access	
Service Level Agreement		
3	Marina managers may wish to draft one.	
Jet Skis prohibited		
	Is this necessary and why?	

Abusive behaviour		
	Will not be tolerated and a solution is being sought	

Date	Further observations/information
	Suggestion
	Female toilets and showers Disabled/Family rooms Male toilets and showers
	on left Centre on right
	Would a short term solution be to put temp blocks
	on north side
T T	
	Need to report to berth holders with a contact e mail
	Also the gate lock needs replacing with one
	that works all the time.Iwan aware
	Has already been done by David O Neill
	Has already been done by David O Neill

